

FIELD INSPECTION REPORT

Date of Inspection :	25.12.2020	District:	Muzaffarpur
Division :	Muzaffarpur East-01	Length (km):	
Name of the Road:	Jahagiopur to Haha Bazar		
Scheme/Programme:	MAINTENANCE	M/R-	3054
Package No.:		Road Id No.:	31507208089
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Jahagiopur to Haha Road ID-31507202388 L-3.050 KM
 Jahagiopur to Haha Bazar Road ID-31507208089 L-2.50 KM
 Both are same road.

NAME:

DESIGNATION:

(Signature)

05-12-2020
 Brahmdeo Prasad
 JE