FIELD INSPECTION REPORT

	The state of the s		
	spection: 5/12/20 District: Murafferpur	11	
Division :	Mysafferpur Cary of Longth (km): 2.57 by	calling	,
Name of	the Road: Siwang to kenya Johan Ma Fancing		•
Scheme/I	Programme: MAINTENANCE Pond III No.: New Major	Lainera	y Par
Package	Myrafferpur Cent of Length (km): 3.37 erg the Road: Siwana to kenya Inar ria Pancha Programme: MAINTENANCE No.: Road Id No.: New Main The Project: Ongoing/Completed/Under Maintenance		
Status of	the Project: Ongoing/Completes and Ingradation/ Maintenance		
Work is	Parameters to be checked	Remarks	
SI. No.	Parameters to be enected		
1.	Pavement	S/U	1 .
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
-	Riding Quality		
c)		S/U	11.
d)	Road Camber Whether free from defects such as visible cracks, exposed	Yes/No	INO
c)	aggregates in case of CC Pavement.		St
-	Contraction Joints provided or not (CC Pavement)	Yes/No	124
U)		Yes/No	
g)	Compaction of flank/slope & raincuts if any	•] [
2.	Cross Drainage	S/SRI/U	11
a)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	41
<u> </u>	Condition of railings/slab/approach for Bridges	S/SRI/U	
c)			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	<u> </u>	_
a)	Status of ATR's & any others	No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U))

NIA

NAME:

DESIGNATION:

Scanned with CamScanner -