## FIELD INSPECTION REPORT

ate of Ir	ispection: \$6/12/24 District:	Veishali	
ivision :	Heibur Length (	(km): 1·5	
Vame of	the Road: Mauna P. WD Roed	to Rammett.	
Scheme/I	Programme: MAINTENANCE		
'ackage			
	the Project: Ongoing/Completed/Under Ma		
Work is	a case of: New Connectivity/Up gradation	on/ Maintenance	Remarks
Sl. No.	Parameters to be cheeke	ers to be checked	
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		s/U
c)	Riding Quality		S/U
d)	Road Camber		S/U .
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
(l)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
(b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		s/SRI/U
3.	Road Furniture		,
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		д

Overall Rating

·	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	- 1

A 6/12/20

(Signature)

NAME: Punit landinger-

DESIGNATION: 7.E