

FIELD INSPECTION REPORT

Date of Inspection: 08/08/20
 Division: Mahara
 Name of the Road: Sitta Yogi, then to Kala Bhat Primary School
 Scheme/Programme: MAINTENANCE
 Package No.:
 Status of the Project: Road ID No.:
 Work is a case of: Upgrading/Completed/Under Maintenance
 New Construction/Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N/A
f)	Construction joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & rainouts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	only info N/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Kinki Kumar

DESIGNATION: JE