

FIELD INSPECTION REPORT

Date of Inspection :	31/12/20	District :	Chitradurga
Division :	Maharajpet	Length (km):	
Name of the Road:	Housing from 10th to 15th km bridge constructed in Tangedu Taluk		
Scheme/Programme:	MAINTENANCE		
Package No.:	NE 10.00/maint / - 97	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	NA S/U
b)	Condition of Surfacing	NA S/U
c)	Riding Quality	NA S/U
d)	Road Camber	NA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

work not started.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SHRAVAN Kumar PRASAD

DESIGNATION: A. E. R. W. D.

(Signature) 07.12.2020