

# FIELD INSPECTION REPORT

Date of Inspection :	04.12.20	District:	Vaishali
Division :	MAHAR	Length (km):	2.172
Name of the Road:	Sarmastpur R.O. Road to Bharon		
Scheme/Programme:	MAINTENANCE	MR (3054)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Work Not Started</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NA
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*[Signature]*  
(Signature)

NAME:

DESIGNATION: AE. Mahnar