

FIELD INSPECTION REPORT

Date of Inspection:	5-12-20	Division:	Madurai
Length (km):	3.70 KM	Name of the Road:	Madurai via Aithur to Sathiyamangudi (New Madurai Bypass)
Scheme/Programme:	MAINTENANCE	Package No.:	HRN/19-20 HRN/19-20
Status of the Project:	Ongoing/Completed/Under Maintenance	Road Id No.:	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Work has not started.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
5/12/20

(Signature)

NAME: *Brajesh Kumar*

DESIGNATION: *AE*
Jandala