FIELD INSPECTION REPORT

Date of Inspection : 05/12/20		**District:** Vaishali	
Division : Mahnar		**Length (km):** 1.600 km	
Name of the Road: House of Ramsawarth Rai to Bhatnar Mohiuddinpur Hindmand High School via Mahadalit Basti			
Scheme/Programme:	MAINTENANCE MR (3054)		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance Work Not Started		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	**Pavement**		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	**Cross Drainage**		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	**Road Furniture**		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NA
4.	**Compliance History**		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)		NA
Satisfactory but requires Improvement (SRI)	/	
Unsatisfactory (U)		

05/12/20

(Signature)

NAME:

DESIGNATION: JE Mahnar