

FIELD INSPECTION REPORT

| | | |
|--|---|---|
| Date of Inspection: 05.12.2020 | | District:- Sitamarhi. |
| Division:- RWD, Works Div. Pupri. | | Length (km):- 2.33 |
| Name of the Road:- Bahera chowk to Majhaur | | |
| Scheme/Programme:- | | MAINTENANCE |
| Package No.:- MR (3054) | | Road Id No.: 31607808053 |
| Status of the Project: | | Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> |
| Work is a case of: | | New Connectivity/Up gradation/ Maintenance |
| Sl. No. | Parameters to be checked | Remarks |
| 1. | Pavement | |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U N/A |
| b) | Condition of Abutments & Wing walls, Slab in RCC culverts | S/SRI/U N/A |
| c) | Condition of railing/slab/approach for bridges | S/SRI/U N/A |
| 3. | Road Furniture | |
| a) | Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained | Yes/No <input checked="" type="checkbox"/> |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | NO |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | SRI |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Name:- Praveen K. Pandey

(Signature)

DESIGNATION:- JE