FIELD INSPECTION REPORT

| Date of Inspection:05.12.2020 | | | District:- Sitamarhi. | |
|----------------------------------|---|-----------------|---------------------------|--------------|
| Division: RWD. Works Div. Pupri. | | | Length (km):-2.400 | |
| Name of | the Road:- Sl | ree khandi bhit | ha barki ke kantahi pokh | ar se chotki |
| hithha t | | | | |
| scheme/l | Programme:- | MAINTE | NANCE | 00050 |
| ackage | No.:- MR (30 |)54) | Road Id No.: 316078 | |
| | the Project: | Ongoing/Comp | oleted/Under Maintenance | |
| | a case of: | New Connectiv | ity/Up gradation/ Mainter | nance |
| Sl. No. | | Parameters to b | e checked | Remarks |
| 1 | Pavement | B | | afa: |
| a) | Road Junction condition | | | S/U |
| b) | Condition of Surfacing | | | √8/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | √S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | | Yes/No |
| f) | Contraction | Loints provided | or not (CC Pavement) | Yes/No |
| | Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any | | | Yes/No |
| g) 2. | Cross Draina | | | |
| a) | Condition of head walls in Hume pipe culverts S/SRI/ including its painting | | | S/SRI/U |
| b) | Condition of Abutments & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| c) | Condition of railing/slab/approach for bridges | | | S/SRI/U |
| 3. | Road Furniture | | | |
| a) | Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained | | | Yes/No |
| 4. | Compliance History | | | 1 110 |
| a) | | R's & any other | ·s | , No |

Overall Rating

| Satisfactory (S) | \$ |
|---|----|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Name: - Bijay Kumar Pandey

(Signature)

DESIGNATION:- 38