FIELD INSPECTION REPORT

Date of I	Inspection: 03				
Date of Inspection: 03.12.2020. District:- Sitamarhi Division:-RWD, Works Div. Pupri. Length (km):-1.83				5 Rimi	
Name of	the Road:- Al	NAPUR TOTARA	AM TO 1 TO PIND ROA	D.	
Sahama/	Programme'-	MAINTENA	ANCE		
Package	No .:- MR-NI	19-20 puprilo:	Road Id No.: 31607	901026	
Status of	f the Project:	Ongoing/Comple	ngoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		nance	
Sl. No.	Parameters to be checked Rem			Remarks - Wood	ct
1.	Pavement be startes				1
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				21
f)	Contraction.	ntraction Joints provided or not (CC Pavement)			11/
	Compaction of flank/slope & raincuts if any			Yes/No	
g) 2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts S/SRI/U				
b)	Condition of Abutments & Wing walls, Slab in RCC S/SRI/U				
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained				
4.	Compliance History				
a)	Status of AT	R's & any others			1

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: - Ram Kumar Satyonthi

(Signature)

DESIGNATION:- A-E