## FIELD INSPECTION REPORT

Date of Inspection:05.12.2020			District:- Sitamarhi.		
Division:-RWD, Works Div. Pupri.			Length (km):-1.73		
Name o	f the Road:- NI	H 104 Jamura Br	idge to Sondahi		
Scheme	/Programme:-	MAINTEN	NANCE		
Package		19-20 Pupri/15	Road Id No.: 316079		
Status o	of the Project:	Ongoing/Comp	leted/Under Maintenance	9	
Work is	a case of:	New Connectiv	ity/Up gradation/ Mainte		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a).	Road Junctio	S/U			
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furnitu				
a)	Whether sing Km & 200n provided and	Yes/No			
4.	Compliance l				
a)	Status of ATR's & any others				

Overall Rating :

: Technical bid submitted for New M/R to H.O.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: - Bijay kumor forder

(Signature)

DESIGNATION:- JE