

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: East Champaran
Division : M.R.N.		Length (km): 4.50 km.
Name of the Road: Harsidhi - Jodhpur R.E.O. road to Balua Bhat		
Scheme/Programme: MAINTENANCE		
Package No.: M.R.N/19-20/27	Road Id No.: 31708201029	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition- <i>Not any work in</i>	S/U
b)	Condition of Surfacing <i>good on</i>	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC-Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N/A

As per Sect.

(Signature)

NAME:

Hemanta Das

DESIGNATION:

Asst RWD

Amrta

Scanned with CamScanner