

FIELD INSPECTION REPORT

Date of Inspection:	05/12/2020	District:	East Champaran
Division:	Arany	Length (km):	5.330
Name of the Road:	Barkurwa To Ekdewra		
Scheme/Programme:	MAINTENANCE		
Package No.:	MIR-N/19-20 Arany-16	Road Id No.:	31708202058
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	work is started
a)	Road Junction condition	Pots Filling works
b)	Condition of Surfacing	in going con.
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N/A at present.

(Signature) *464 8/12/20*

NAME: *Hemant Singh*

DESIGNATION: *AE. R.W.D. Arany*

Scanned with CamScanner