FIELD INSPECTION REPORT				
Date of Inspection: 05-12-2020			District: East Champaren	
Division: RWD chedica			Length (Km): 오· 용요구	
Name of the Road: PLAID Road to Kadhan.				
Scheme/Programme : MAINTENANCE				
Package No.: NR-N/15-20 chalcra/15 Road ID No.: 31708202167				2167
Status of	the Project :	Ongoing/Completed/Unc	Under Maintenance	
Work is a case of : New Connectivity/Up Gradation/ Maintenance				
SI. No.	Parameters to be checked Remarks			
1,	Pavement			
a)	Road Junction condition			In progress-
b)	Condition of Surfacing -			
c)	Riding Quality			
d)	Road Camber			
е)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-
f)	Contraction Joints provided or not (CC Pavement)			-
g)	Compaction of flank/slope & raincuts if any			_
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			
4,	Compliance History			
a)	Status of ATR's & any	y others		
	Overall Rating :	Satisfactory (S) Satisfactory but requires Unsatisfactory (U)		2
Remarks: Pot patche and levelling work in progress.  (Signature)				
4	NAME: (Signature)			
	DESIGNATION:	China Sing		
		10		