FIELD INSPECTION REPORT

Date of	Inspection test infrance Districts East Chambaran	
Division	Length (lum): 1,130	-
Nome :	The Read: Glaya Glat Devi Stem To Glaya Ghat Baza	
-	Maria 20 20 Paral 11 Reed Id No. 3/908301024	
	Compling/Completed/Under Maintenance	
	n case of: New Connectivity/Up gradation/ Maintenance	
F 7871	The state of the s	oneselo.
	THE RESERVE BASIS AND SERVED BY	
3	Road Junction condition	8/1/
<u>b)</u>	Condition of Surfacing	8/1
e)	Riding Quality	8/12
d)	Road Camber	8/1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Ð	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	X64/No
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
星三		
	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	ی
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Harridos God

DESIGNATION: ME. RND

greray