		PIELD INSPE	CTION REPORT	
Det	of Inspection		Interest Cast Champara	<u>n</u>
Divi	Date of Inspection : 0 4 12 70 20  Division: Average Name of the Read: 6048 To Karch Schomo/Programme: MAINTENANCE		Longth (km): 1.600	
Nem	e of the Road: LC	ARTA Karhi	Tèla	and the second second second second
Beek	me/Programme:	MAINTENANCE	217.07.07.07.00	
	Me No	And the state of t	Read Id 1904 151 100 50 70	9
Word	of the Project:	Ongoing/Complete	d/Under Maintenance	
40.8	the case of:	New Connectivity	Up gradation/ Maintenance	Remarks
		All Manhammore and the last		Work Nottook
-	Personal	<b>第二十二年</b>		2001
4)	Road Junction	condition	HIM.	S/U
b)	Condition of St	urfacing	HIA	S/U
c)	Riding Quality		N/A	S/U
<b>d</b> )	Road Camber		. N/A	S/U
e)	Whether free	from defects su	ch as visible cracks, exposed	Yes/No
Ð		nts provided or not		Yes/No
g)	1	flank/slope & raino		Yes/No
THE PARTY	The work of the second			
<b>a</b> )			pipe culverts including its painting	s/sri/u
b)	+		valls, Slab in RCC culverts	S/SRI/II
<b>c</b> )	Condition of railings/slab/approach for Bridges			S/SRI/U
	A SE SESSION OF THE S			
a)	stones/Pavement	t road markings ar	y/cautionary Board/km & 200 re provided and maintained	m Yes/No
<b>第二条</b>				
<b>a</b> )	Status of ATR's			No.

**Overall Rating** 

Satisfactory (S)	No
Satisfactory but requires Improvement (SRI)	No
Unsatisfactory (U)	No -

Notice issed has been to contraction.

NAME: Shew Pour Augh

DESIGNATION: SK, SK,

8 HD, 12.9-

Bread