

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: East Champaran
Division : WORKS DIVN DHAKA	Length (km): 3.86 km
Name of the Road: Motihari Dhaka Road to Shitalpathi Road	
Scheme/Programme: MAINTENANCE (New Maintenance Policy - 2018)	
Package No.:	Road Id No.: 31708602114
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO PCC	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any work not done	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U painting not done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Informatory Board not fixed
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	—

NAME: Ramchandra Paswan
DESIGNATION: Executive Engineer

03/12/2020
Executive Engineer
R. W. D. Works Division
(Signature)
DHAKA

&
03/12/20
JE