

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	East Champaran
Division :	WORKS DIVN DHAKA	Length (km):	0.660 km
Name of the Road:	Motihari Dhaka to Partapur		
Scheme/Programme:	MAINTENANCE (New Maintenance Policy - 2018)		
Package No.:		Road Id No.:	31708602173
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO PCC	Yes/No - N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A
g)	Compaction of flank/slope & raincuts if any work not done	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Painting not done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ Informatory Board not fixed
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	✓

NAME:

Ramchandra Paswan

DESIGNATION:

Executive Engineer

03/12/2020
Executive Engineer
R (Signature) s Division
Dhaka

03/12/20
JE