

FIELD INSPECTION REPORT

Date of Inspection :	05.12.2020	District:	W. Champaran
Division :	Bafian	Length (km):	0.92 km
Name of the Road:	Mokaddipur to Bhatta chlg		
Scheme/Programme:	MAINTENANCE		
Package No.:	RN/WP/BET/20/0006	Road Id No.:	31808801006
Status of the Project:	Ongoing/Completed/Under Maintenance		ON GOING
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U✓
b)	Condition of Surfacing	U S/U✓
c)	Riding Quality	U S/U✓
d)	Road Camber	U S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Note:- Agreement dated:- 27.07.2020
work not started

(Signature)
05/12/20

NAME:

DESIGNATION: