

FIELD INSPECTION REPORT

Date of Inspection :	5-12-20	District:	West Champaran
Division :	Narkatiya jang	Length (km):	2.44 km.
Name of the Road:	Dona Canal to Sithi under 3054 MR.		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/WE/NAR/19/0006	Road Id No.:	3/008802080
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓
f)	Contraction Joints provided or not (CC Pavement)	✓
g)	Compaction of flank/slope & raincuts if any	✓
2.	Cross-Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓
c)	Condition of railings/slab/approach for Bridges	✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓
4.	Compliance History	✓
a)	Status of ATR's & any others	✓

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

Note — work not started.

W. S. 5-12-20
(Signature)

NAME: VIJAY PRATAP SINGH

DESIGNATION: J-E