## FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020			District: Int. champanan	
Name of the Road: Sisa: 10			Length (Km): 3-294 Vm	
scheme	Pfogramme:		Ipadhya +81a	
гаскадо	No .: RM/WE			
The state of the s	- sare a rolect:	Ongoing/Completed/Un	ond Id No.: 3/808802/2	2
Work is	a case of:	New Connectivity/Un a	radation/ Maintenance Ong	ding
SI. No.	Parameters to be checked			
1.	Payement Payement			Remarks
a)	Road Junction	condition	Halabia Blancia	Participated Street
b)	Condition of Surfacing			Orgaing
c)	Riding Quality			Orgaing
d)	Road Camber			11
e)	Whether free from defects such as visible cracks, exposed			Ŋ
	aggregates in case of CC Pavement.			NA
f)	Contraction Joints provided or not (CC Pavement)			NA
g)	Compaction of flank/slope & raincuts if any			-
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			NA
c)	Condition of railings/slab/approach for Bridges			NA
3,	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Orgoing
4	Compliance H	story	GRADE CONTRACTOR	
a)	Status of ATR's & any others			-

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME: Jay prokash Ram

DESIGNATION: JUNIOR ENGINEER