## FIELD INSPECTION REPORT

Date of Inspection:	6.12.2020 District: W. Champaran
Division: Retian	Longth (Irm)
Name of the Road: L	028 to Naukatola
Scheme/Programme:	MAINTENANCE
Package No.: RM/ WG	
Status of the Project:	Ongoing/Completed/Under Maintenance ON 902M9.
Work is a case of:	New Connectivity/Up gradation/ Maintenance Haint

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing U	S/U	
c)	Riding Quality	s/u	
d)	Road Camber U	S/U_	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges S/S		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	10,

, Agrenoent of datal: 27.04, 2020 work wit started toll date

(Signature)

NAME:

**DESIGNATION:**