

FIELD INSPECTION REPORT


Date of Inspection : 06.12.2020		District: W. Champaran
Division : Betiah		Length (km): 4.010.4
Name of the Road: Manjhaullia Jodishpur Road to Rampur Bairagi		
Scheme/Programme: MAINTENANCE		
Package No.: EM/WS/BET/20/0006		Road Id No.: 31808802146
Status of the Project: Ongoing/Completed/Under Maintenance ONGOING.		
Work is a case of: New Connectivity/Up gradation/ Maintenance Maint.		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	U S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	NO Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	'U'

Agreement on dated :- 27.07.2020
work not started till date


(Signature)

NAME:

DESIGNATION: