## FIELD INSPECTION REPORT

| Date of l | Inspection: 06   | -12.2020           | District: W. Ch        | 24/200    | 20            |
|-----------|--|--------------------|------------------------|-----------|---------------|
| DIAISION  | Betiah   |                    | Length Combo           | A 16 . 1  |               |
| Name of   | the Road: Ja   | risky RT Pd        | to Mushahra Ba         | un 10 a F |               |
|           | of amme:   | MAINTENANCE        | Te MAZERA DE           | 111600    |               |
| Package   | No.: RM/ WE  | BET/19/0020        | Road Id No.: 3180      | 88021.    | 52            |
| Status o  | f the Project:   | Ongoing/Completed  | /Under Maintenance     | DNCAD     | 110           |
| Work is   | a case of:   | New Connectivity/U | Jp gradation/ Maintena | nce Mair  | Tenance       |
| Sl. No.   | Parameters to be checked   |                    |                        |           | Remarks       |
| 1.        | Pavement   |                    |                        |           | <del>1 </del> |
| a)        | Road Junction  | condition          |                        | τ         | S/U           |
| b)        | Condition of S   | urfacing           |                        | ひ         | S/U~          |
| c)        | Riding Quality   |                    |                        | U         | S/U~          |
| d)        | Road Camber  |                    |                        | V         | S/U~          |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         |                    |                        |           |               |
| f)        | Contraction Joints provided or not (CC Pavement)  NA Yes/No  |                    |                        |           |               |
| g)        | Compaction of flank/slope & raincuts if any  Yes/No  |                    |                        |           |               |
| 2.        | Cross Drainag  | je                 |                        |           |               |
| a)        | Condition of head walls in Hume pipe culverts including its painting   |                    |                        |           | S/SRI/U       |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts   |                    |                        |           | S/SRI/U       |
| c)        | Condition of railings/slab/approach for Bridges  |                    |                        |           | S/SRI/U       |
| 3.        | Road Furnitur  | re _               |                        |           |               |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                    |                        |           | Yes/No        |
| 4.        | Compliance H   | istory             |                        |           |               |
| a)        | Status of ATR's  | s & any others     |                        |           | NO            |
| a)        | Status of ATR's  | s & any others     |                        |           | NO            |

Overall Rating

| Satisfactory (S)                            |   |
|---|---|
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | Ų |

Agrenoentle Patel: 30.05.2000 NOORK not Hart & till date

Signature)

NAME:

**DESIGNATION:**