

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	West Champaran
Division :	R. WD Bethah	Length (km):	0.6
Name of the Road:	Muz Pur Dubaria to Basma		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	MR-N/19-22 Bethah-25	Road Id No.:	31808802040
Status of the Project:	Ongoing/Completed/Under Maintenance In Agreement Process.		
Work is a case of:	New Connectivity/Up gradation/ Maintenance work not started		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : In Agreement Process work not started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature) 4/12/20

NAME: Haseeb Iman

DESIGNATION: Junior Engineer