


FIELD INSPECTION REPORT

Date of Inspection : 06/12/2020		District: N. Changanur
Division : Betiah		Length (km):
Name of the Road: Betiah Avenge Pith Rd. to Karuati Seng Moli Lani Pith Rd.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31808808053
Status of the Project: Ongoing/Completed/Under Maintenance		UNDBR Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maintenance

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/O
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/O.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: SONIL KUMAR

DESIGNATION: J E