## FIELD INSPECTION REPORT

Date of Inspection: 6	112/2020	District: W. Flanbaran		
Division: Betian		Length (km): 0.740km		
Name of the Road:	rogalatti Slock	office to soli Bozar		
Scheme/Programme: (MAINTENANCE)				
Package No.:		Road Id No.: 31808808056		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

St. No.	Parameters to be checked	
1.	Payement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing U	S/U
c)	Riding Quality U	S/U/
d)	Road Camber	S/U _
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
*	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Read Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: Ram Onlar charlas DESIGNATION: Junior Engineer