FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District: West Chramparsan	
Division: Bagaha-2		Length (km): 1.6 km	
Name of the Road.	Dichi to on	ushari	
Scheme/Programme:	MAINTENANCE		
Package No.:	/	Road Id No.: 3/809/02009	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

TOTAL ES	a case of: New Connectivity/Op gradation/ Maintenance			
SI. No.	Parameters to be checked			
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
n	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any	_Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting \S/SRI/L			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History	ND		
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	Salesando
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Digambar Jkg
DESIGNATION: Assistant Engineer