


FIELD INSPECTION REPORT

Date of Inspection : 3/12/20	District: West Champaran
Division : Bagaha - 2	Length (km): 4.45 km
Name of the Road: Temkheha to Barwa	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 31809102037
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition S	✓S/U
b)	Condition of Surfacing S	✓S/U
c)	Riding Quality S	✓S/U
d)	Road Camber S	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any Y	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges S	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Y	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 (Signature) AE

NAME: Digambar Jha
 DESIGNATION: Assistant Engineer