

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District:	Darbhanga
Division :	RWD Darbhanga	Length (km):	2.250
Name of the Road:	RBO Road Talwar to Raja Rouli.		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance Transfer to PMGSY-II		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		NA
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Road is Dropped Covered by PMGSY-II.

Shams Ahmad
(Signature)

NAME: SHAMS AHMAD
AE