Date of Inspection:		oG 12 2020	36 The St. St. St. and Appear and Appear and the Company of the	Dayllman	
Division:		Dorkhanga. 2	1 5	Dorlehanga	
Name of Road:		Dinanga 2	Length(Km):	2.350	
Scheme/Progrmme:		Paris read Charge chown to kataia-			
1100		Maintenance			
Package No.		Road Id No.		- Martin S. W. W. Art St. etc.	
Status of the Project:		Ongoing/Completed/ Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
CMo				projection of expenditure	
		arameters to be Checc	Remarks		
1	Pavement				
a) b)	Road Junction condition			S/U	
c)	Condition of Surfacing Riding Quality			S/U	
d)	Road Camber			S/U S/U	
e)	Whether free from defects such as visible cracks, exposed			3/0	
	aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank /slope & raincuts if any			Yes/No	
2	Cross Draina	ross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U	
3		Road Furniture			
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and			Yes/No	
	maintained				
3	Complianace History				
' a)	Status of ATR's & any others			V - 2604	
Overa	ll Rating:			January Spanish Comments	
*	Satisfactory (S)				
		Satisfactory but requires Improvement (SRI)		Modern Line	
		Unsatisfactory (U)		1 1 1 17	

Hara Rom

NOTE: 1- This read has been ganchern in p.m.a.s. 4. plage-11, and work suither storted, combleted approx Dec. 2023