

## FIELD INSPECTION REPORT


Date of Inspection:	06.12.2020	District:	Darbhanga.
Division:	RWD Writas (Div) Darbhanga-2.	Length(Km):	3.35 km.
Name of Road:	Rasulpur pWD Road to Sozaiya.		
Scheme/Programme:	Maintenance New Maint. Policy - 2018, Head - 3054.		
Package No.	_____	Road Id No.	_____
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

Name: KUMAR CHANDRAJ  
Designation: ASST. ENGINEER.

  
 (Signature)  
 सहायक अभियन्ता  
 ग्रामीण कार्य विभाग  
 कार्य अवर प्रमंडल, सिंहबाड़ा