

## FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	RWD W (Div.) Darbhanga-2	Length(Km):	0.273 KM
Name of Road:	Const. of road rep. from PWD path Singhmura to Singhmura hospital path.		
Scheme/Programme:	Maintenance OLD MR.		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance —		
Work is a case of :	New Connectivity/Up gradation/ Maintenance —		

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank /slope & raincuts if any	Yes/No NA
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
<b>3</b>	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No NA
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA


Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Not applicable ✓

Name:

Designation:

  
 S. K. Singh  
 सिन्हासक अभियन्ता  
 ग्रामीण कार्य विभाग  
 कार्य अवर प्रमंडल, सिन्हाबाड़ा