

FIELD INSPECTION REPORT

Date of Inspection : 05.12.20

District: Madhubani

Division : Madhubani

Length (km): 1.130 Km

Name of the Road: NH to Jhda Tol

Scheme Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project:

☒ Complete Under Maintenance

Work is a case of:

☒ New Connectivity ☐ Upgradation ☐ Maintenance


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No ATR read

Rectification work yet to be started
Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Ram Nath Singh.

NAME:


5.12.20.
(Signature)