FIELD INSPECTION REPORT Date of Inspection: Division: Syrnarty Pur (Kalyanfur Length (km): District: Symastipuz 3.700 Km Bhalfi chrowk to Bakhari Scheme/Programme: MAINTENANCE Package No.: Status of the Project: Road Id No.: 320 10 10 10 13 Ongoing/Completed/Under Maintenance (Work not started) Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked Remarks 1. Pavement Road Junction condition a) S/U b) Condition of Surfacing S/U c) Riding Quality S/U d) Road Camber S/U Whether free from defects such as visible cracks, exposed e) Yes/No aggregates in case of CC Pavement. NA Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) Yes/No 2. Cross Drainage Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U Condition of railings/slab/approach for Bridges c) S/SRI/U 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m a) stones/Pavement road markings are provided and maintained Yes/No Compliance History 4. NA Status of ATR's & any others a) Overall Rating Satisfactory (S) NA

Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Chandra Kurnaz Mishra