		FIELD INSPEC	TION REPORT		
Date of I	nspection: 0				
Division: Canada Marianta Mari					
Name of	the Road:	2 (Khanpuz)	Length (km): 50	0-250	
Scheme/l	Programme:	MAINTENANCE	intpus		
Package	No.:	THATEINANCE			
Status of	the Project:	Ongoing/Completed	Road Id No.: 3201010208	32	1
		/Under Maintenance (Work r Jp gradation/ Maintenance	10T Starley	,	
Sl. No.		Parameters to		Remarks	
1.	Pavement				
a)	Road Junction	S/U -	7		
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free aggregates in	Yes/No	NA		
f)	Contraction Jo	Yes/No			
g)	Compaction o	Yes/No			
2.	Cross Drainage				
a)	Condition of h	S/SRI/U			
b)	Condition of A	S/SRI/U	NO		
c)	Condition of r	S/SRI/U	NA		
3.	Road Furniture				
a)	Whether sign stones/Paveme	Yes/No			
4.	Compliance 1		No		
a)	Status of ATR's & any others				7

Overall Rating

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Gautam Das (JE)