		- SCIIO	N REPURI		
Date of	f Inspection:	06/12/2020 Dist	trict: Samantifuz		
Division: Samenti Pun Length (kg			igth (km): 2.700 KM		
	of the Road:		Schmalfuz_		
	c/Programme:	MAINITENIANICE	out of maintaine		
Packag			d Id No.: 3201010806	2-	
Status o	of the Project:	Ongoing/Completed/Und	er Maintenance	2 1 maintes	
. 110 50	s a case of:	New Connectivity/Up gra	dation/ Maintenance		
Sl. No.		Parameters to be ch		Remarks	
<b>1.</b>	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
<u>c)</u>	Riding Quality			S/U	
d)	Road Camber .			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	(e			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
01 1	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance Hi	story			
a) !	Status of ATR's & any others			NA	

Overall Rating

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: RISHI RAJ (JE)