## FIELD INSPECTION REPORT

Date of	Inspection : C	6-12-2020	District: Samastipur	/
The state of the s				
Name o	f the Road: P	of Good Gon	Length (km): Sarani Madhopur	
paragraph of the comment of the comm	71 rogramme:	MAINTENANCE		
Packago	-		Road Id No.:	
Status of the Project: Work is a case of:		The second secon	I/Under Maintenance	- Mainte
	a case of:	New Connectivity/U	Jp gradation/ Maintenance	
Sl. No.		Parameters to be checked Remarks		
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber .			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	Tentra Carlo (E.C.)

NAME: Ajey Kermer Sirgh Stynoblishase
A. E

(Signature)

DESIGNATION: J.E.