

FIELD INSPECTION REPORT

Date of Inspection : 04/12/20	District: Samastipur
Division : PATOR	Length (km): 1.50 KM
Name of the Road: KARIMNAGAR TO HASNI	
Scheme/Programme: MAINTENANCE	
Package No.: N/A	Road Id No.: N/A
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/M
b)	Condition of Surfacing	S/M
c)	Riding Quality	S/M
d)	Road Camber	S/M
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	SATISFACTORY(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shyam
04/12/20
(Signature)

NAME: SHYAM NANDAN KUMAR

DESIGNATION: ASSISTANT ENGINEER

04/12/20