



FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 2.280	
Name of Road :MDR to Rampur Jalalpur			
Scheme / Programme:		MAINTENANCE	
Package No:RM/SA/DAL/19/004		Road Id No: -	
Status of the Project: Work Has not Started			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition		
b)	Condition of Surfacing	"U"	
c)	Riding Quality	"U"	
d)	Road Camber	"U"	
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	"U"	
e)	Constraction Joint provided or not(CC Pavement)	No	
f)	Compaction of flank/slope & raincuts if any	NO	
g)		-	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	"U"	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridge	-	
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No	
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory(S)	"U"
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-


 24/12/20
 (Signature)


 4.12.20

NAME: Deepak Chandra Sinha
 DESIGNATION : Junior Engineer