

FIELD INSPECTION REPORT


Date of Inspection: 04/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.700
Name of Road :Construction of Road from Ghatho Dayal Chowk se Bhatgawan kali Asthan se Bhatgama Prathmic vidyalaya hote hue Khagutiya Bandh tak		
Scheme / Programme:		MAINTENANCE
Package No:--RM/SA/DAL/19/004		Road Id No: --
Status of the Project: Work Has not Started		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	"U"
b)	Condition of Surfacing	"U"
c)	Riding Quality	"U"
d)	Road Camber	"U"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NO
f)	Constraction Joint provided or not(CC Pavement)	NO
g)	Compaction of flank/slope & raincuts if any	-
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	"U"
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES
4	Compliance History	
a)	Status of ATR's & any others	NO


Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement(SRI)	"SRI"
Unsatisfactory(U)	-

Work has been not started till now

NAME: Deepak Chandra Sinha
DESIGNATION : Junior Engineer


 04/12/XX
 (Signature)


 4.12.20