FIELD INSPECTION REPORT

Date of Inspection: 07.12-222 District: Beg.usarai

Division: Manikaw - Bakhti Length (km): 1.250

Name of the Road: Paksara Bagras in Brindanon state Tubertal Road

Scheme/Programme: MAINTENANCE

Package No.: Road Id No.: 32010503102

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 7
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	•

Overall Rating

Satisfactory (S)	18
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) JE

NAME: SHRIKANT VIDYARTHS

DESIGNATION: 52