

FIELD INSPECTION REPORT

Date of Inspection : 6-12-2020	District: Begusarai.
Division :	Length (km): 0.360 km.
Name of the Road: Const. of PCC road from H. School Maghaur to Bedulia	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 3240808014
Status of the Project: Ongoing/Completed/Under Maintenance	out of maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	out of maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U out of maintenance
b)	Condition of Surfacing	S/U "
c)	Riding Quality	S/U "
d)	Road Camber	S/U "
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No "
f)	Contraction Joints provided or not (CC Pavement)	Yes/No "
g)	Compaction of flank/slope & raincuts if any	Yes/No "
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U "
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U "
c)	Condition of railings/slab/approach for Bridges	S/SRI/U "
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No "
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	out of maintenance
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
6/12/20
(Signature)

NAME: S.M. Amir Haque.

DESIGNATION: J.E