## FIELD INSPECTION REPORT

Date of Inspection: 7-12270.			District: Beguserei	
Division: manyhor Banksi'			Length (km): 2.20 KM	
Name of th	e Road: Me	intense Broad for	m khadevanper Ratchard Sc	2 Musheri
		MAINTENANCE		
Package No.:			Road Id No.: 32010 808026	
Status of tl	ie Project:	Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity		New Connectivity/	Up gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1. F	Pavement		A survey of survey of	1601 374
a) F	Road Junction			<b>V</b> S/U
b) (	Condition of Surfacing		<b>∨</b> S/U	
	Riding Quality			✓S/U
				✓ <sub>S/U</sub>

Whether free from defects such as visible cracks, exposed

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

aggregates in case of CC Pavement.

Cross Drainage

Road Furniture

Compliance History

Status of ATR's & any others

Contraction Joints provided or not (CC Pavement)

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Overall	Rating
---------	--------

e)

f)

g)

2.

a)

b)

c)

3.

a)

4.

a)

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	×
Unsatisfactory (U)	×

(Signature)

Yes/Nov

Yes/No V

✓Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No

No

NAME: S.M. Aminul Hague DESIGNATION: Junear Engineer