## FIELD INSPECTION REPORT

Date of Inspection: 67-12-2020		District: Begusara	
Division: Manihaul · Bakhri		Length (km): 14.950	
Name of the Road: pe	hsara to Ba	gras Road	
Scheme/Programme:			
Package No.:		Road Id No.: 32010808032	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	<b>√</b> 5/U	
b)	Condition of Surfacing	√S/U	
c)	Riding Quality	J\$/U	
d)	Road Camber	<b>.</b> 8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
ſ)	Contraction Joints provided or not (CC Pavement)	Yes/No/	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-∕\$/SRI/U	
c)	Condition of railings/slab/approach for Bridges	∽Ś/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ýes/No	
4.4	Compliance History		
a)	Status of ATR's & any others	100	

Overall Rating :

Satisfactory (S)	S .
Satisfactory but requires Improvement (SRI)	y
Unsatisfactory (U)	×

(Signature)

NAME: SHRIKANT VIDYARTHS

DESIGNATION: JUNIOR ENLINEER