FIELD INSPECTION REPORT

Dat	e of Inspection: C	5-12-2020	District: Craya	
DIV	ision: Sheraha	h'	Length (km):	
Nan	ne of the Road; G.	Road Sulebat	Ha to Dhamana Via Time MR 3054	in'chark
	kage No.:	THE REAL PROPERTY.	Road Id No.:	
		Ongoing/Complete	ed/Under Maintenance	
	k is a case of:	New Connectivity/	Up gradation/ Maintenance	
SI. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction	condition		*Ś/U
b)	Condition of St	ırfacing	in brugtess	S/U
c) Riding Quality				SU
d)	Road Camber	NAME:		S/U
e)		from defects such se of CC Pavement.	h as visible cracks, exposed	Yes/No
f)	Contraction Join	its provided or not (CC Pavement)	Yes/No
g)	Compaction of f	lank/slope & raincu	ts if any in progress	Yes/No
2.	Cross Drainage			
a)	Condition of hea	d walls in Hume pip	ne culverts including its painting	S/SRI/U
b)	Condition of Abu	tment & Wing wall	ls, Slab in RCC culverts	S/SRI/U N
:)	Condition of railings/slab/approach for Bri		or Bridges	S/SRI/U N
	Road Furniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance History			1000
	Status of ATR's &	any others		

Overall Rating

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

(Signature)