

FIELD INSPECTION REPORT

Birsa - Sultanpur

Date of Inspection : 6.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 12.75 Km	
Name of the Road : Repair of road from Alhuganj to Kurmaitha.			
Scheme / Programme : MAINTENANCE			
Package No : —		Road Id No. : 20703208224	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Condition of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating :			
Satisfactory (S)		/	
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)		/	

Not → Road furniture not painted properly. Some patches are developed in the Road Surface.

NAME: D.N. Dasm.

DESIGNATION: J.E

(Signature) *Ch* 6/12/20