

FIELD INSPECTION REPORT

Date of Inspection : 6.12.2020. | District : Bhagalpur
 Division : Bhagalpur | Length (Km) : 2.130
 Name of the Road : Repair of Asarganj Shambuganj PWD road to Siyachik via Dhanda (Bihar).
 Scheme / Programme : MAINTENANCE
 Package No. : | Road Id No. : 20703208226
 Status of the Project : | Ongoing / Completed / Under Maintenance
 Work is a case of : | New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes / No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes / No
g)	Condition of flank/slope & raincuts if any	✓Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards / informative / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating : -		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

Note - Board Painting Not Properly & No Grass Cutting Not maintained.

NAME: Rajeshwar Kishor
 DESIGNATION: AE

(Signature) 
 6.12.2020
 AE

AE
 4/12/20