

# FIELD INSPECTION REPORT

(Block - Shahkud)

Date of Inspection : 04/12/2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) :	
Name of the Road : Repair of road from Shivshankarpur Mor to Regra via Sajaur Rasthanger.			
Scheme / Programme : MAINTENANCE		(old MP)	
Package No. :		Road Id No. : 20703208228	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S / U	S
b)	Condition of Surfacing	S / U	S
c)	Riding Quality	S / U	S
d)	Road Camber	S / U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes / No	No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	SRI
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	S
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	S
3.	<b>Road Furniture</b>		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	Yes
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others	No	
Overall Rating :			
	Satisfactory (S)	—	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	—	

Note :

NAME : Radhe Raman Singh  
 DESIGNATION : Assistant Engineer

  
 04/12/2020  
 Signature